## BREM: COLOR LIST THIS COLORS LIST SHOULD BE USED ONLY AS A GUIDE; CONSULT THE BREM COLORS CARD IN OUR SALES OUTLET

SB 9016 Standard white SABLÈ (C-PROLUX excluded) Ral 9016 SPECIFY IN THE ORDER (Standard only for C-Prolux)	NDARD COLOR Without extra (see models)	SB 9010 Pure white SABLÉ: SPECIFY IN THE ORDER Color on request without extra (C-PROLUX excluded)
RAL 9002 Grey white	Selection of RAL colors available in various finishes: brillant, satin, opaque and softTOUCH.	RAL 9010 Pure white
RAL 7047 Grey Chinchilla	BRIGHT +15% COLORS 75-85GU ±5 E.g. Ral 9002	RAL 9001 Cream White
RAL 7038 Agate grey	Ŭ	RAL 1013 Oyster white
RAL 7044 Silk grey RAL 7030 Stone grey	SATIN +25%	11600 Pergamon RAL 1015 Light ivory
RAL 7006 Grayish beige	COLORS ± 60GU ±5 E.g. Rdl 9002-S	RAL 1017 Saffron yellow
RAL 7036 Platinum grey		RAL 3000 Flame red
RAL 7037 Dusty grey	SoftTOUCH±5GU COLORS +25%	RAL 3003 Rubies red
RAL 7015 Slate grey RAL 5013 Cobalt blue	Velveteen and soft touch finish, easy to clean, fingerprint and abrasion resistant. E.g. Ral 9002-ST	RAL 3005 Wine red RAL 4005 Purple lilac

## COLORS FOR ARCHITECTURE: 180 RAL COLORS IN VARIOUS FINISHES colors out of Brem list: +25%, + cost contribution upon availability and feasibility

RAL	9016-M	White	(matt)

RAL 9010-M Pure white (matt)

OPAQUE +15% COLORSmatt 30gu

RAL 9005-M Jet black (matt)


RAL 9005 BRILLIANT (on request only for same model)

## SPECIAL FINISHES +35%

- BR 0031 only for panels, Cross, Essen, Quar and Pit, is a brushed-metal effect to hide scratches on the surface, clear varnish. (BR 0007 is the color that both comes

closest to natural iron and best conceals imperfections). - BR 0021 transparent polished finish, it transmits the brass effect, glimpsing weldings.

- SB 0022 BL polished and nuanced rust color finish that perfectly fits with the gilded leaf finishes (Eruzione)



BR 0022 BL Bright rust (shaded color)

BREM SPECIAL FINISHES (panels excluded) - BR 0001, a transparent metallic bright finish, highlights the signs of working on iron (welding, scoring, brushing, rings, marks, etc.); the phosphate greasing process enhances the colors of steel in shades of grey, blue, brown, and dark green, and makes each piece unlike any other. This finish is a good example of "Poor Art" and it is not available for the radiating plates. - BR 0001 MS, a clear matte finish, transmits all the raw material's "brutality", whereas a shiny finish softens the look (not available for radiating plates).